Dr. Henry Ridgely House (Crawford House) 6 S. State Street Dover Kent County Delaware HABS No. DE-177

HABS DEL, !- DOV,

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

ACHERICA POLLAVIS

Historic American Buildings Survey National Park Service Department of the Interior Washington, D.C. 20240

United States Department of the Interior National Park Service Washington, D.C. 20240

HISTORIC AMERICAN BUILDINGS SURVEY

ARCHITECTURAL DATA FORM

DEL, 1-DOV,

				(0-
STATE	COUNTY		TOWN OR VICINITY	
Pelaware	Kent		Dover	
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME)			HABS NO.	
Dr. Henry Ridgely House				DE-177
SECONDARY OR COMMON NAMES OF STRUCTURE				
Crawford House				
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES)				
6 S. State Street				
DATE OF CONSTRUCTION (INCLUDE SOURCE) ARCHITECT(S) (INCLUDE SOURCE)				
1869				
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE)				
This fine Italianate house was built for Dr. Henry Ridgely in 1869. The July 31, 1869, Delawarean noted, "The fine brick mansion of Dr. Ridgely will soon be completed."				
Della wair can in out a, the billion and a second a second and a second a second and a second a second and a second and a second and a				
STYLE (IF APPROPRIATE)				
Italianate				
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) Brick bearing walls and center cross interior walls with wood framing. Running bond with				
red stones at quoins.				
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE) T-shaped; approximately 54'x42' with brick wing 21'x40', with wood frame wing on that				
1'x27'. Three stories with five-story tower. One-story 15'x15' wing on north.				
EXTERIOR FEATURES OF NOTE Square tower in center of front with mansard roof; cornice has dentils and paired consoles;				
wooden porch across front with arched openings between box columns, fan brackets; one-story wooden bays on south side of house, north side of rear wing; porch on south side of rear				
wing now enclosed to form solarium; windows round- and segmental-arched with bracketed hoods.				
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)				
Plaster cornices in main rooms; plaster ceiling medallion in parlor (south room); brown				
marble mantels.				
MAJOR ALTERATIONS AND ADDITIONS WITH DATES				
PROOF ALIERATIONS AND ADDITIONS WITH DATES				
<u> </u>				
PRESENT CONDITION AND USE				
Private residence and rooming house				
OTHER INFORMATION AS APPROPRIATE				
Hexagonal wrought-iron gazebo on north side house; wood-frame privy northwest of house.				
SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)				
John P. White, Project Supervisor for HABS, draft description, 1975.				
COMPILER, AFFILIATION			 ·	DATE
		42.74		Tanuar 1082
Alison K. Hoagland, Historic	American Bu	uldings Surv e y		January 1983

HABS No. DE-177 10-

Addendum to:
Dr. Henry Ridgely House
6 South State Street
Dover
Kent County
Delaware

PHOTOGRAPHS

HISTORIC AMERICAN BUILDINGS SURVEY
MID-ATLANTIC REGION NATIONAL PARK SERVICE
DEPARTMENT OF THE INTERIOR
PHILADELPHIA, PENNSYLVANIA 19106

ALDENDÚM FOLLOWS.... ADDENDUM TO
DR. HENRY RIDGELY HOUSE
(CRAWFORD HOUSE)
6 South State Street
Dover
Kent County
Delaware

HABS NO. DE-177
HABS
DEL,
I-DOV,
10-

XEROGRAPHIC COPIES OF COLOR TRANSPARENCIES

HISTORIC AMERICAN BUILDINGS SURVEY
National Park Service
U.S. Department of the Interior
Washington, D.C. 20013